# ALUMINUM TYPE-C MULTIMEDIA ADAPTER

1 Connect Type-C adapter to USB-C port on your laptop.
USB-C laptops must support both DisplayPort over USB-C (Alt mode) and USB-C Power Delivery (2.0 or higher)

2 Connect laptop power adapter to USB-C charging port.
Max output — 49W

3 Use HDMI cable to connect external monitor to HDMI port.
Display will be mirrored on HDMI monitor.
Resolution up to 4K @ 30Hz

HDMI
4K

4 Connect external monitor to mini DP port with DP cable.
Display will be mirrored on mini DP monitor.
Resolution up to 4K @ 30Hz

4K

5 Connect Ethernet cable to Ethernet port.
Supports 10/100/1000Mbps

6 Connect USB peripherals to USB 3.0 ports.
Use 1 hard drive at a time. Does not charge iPad.

7 Insert Micro SD or SD card into card reader slots. Data speeds up to 104 Mb/s

OPERATING TEMPERATURE IS 86-122°F